



County Road 318 - View North –pot holes- pavement cracks



County Road 318 – Pavement Surface – Showing Surface Condition and Wheel Ruts



County Road 318 – Typical Industry Traffic



County Road 318 – Pavement Surface – Showing Surface Condition and Wheel Ruts



County Road 207 – Lightner Creek Bridge – Before replacement in 2013



County Road 207 – Lightner Creek Bridge – New Bridge in 2013



County Road 213 – Reconstruction in 2005



County Road 213 – Reconstruction in 2008 below Basin Creek



County Road 213 – Lower La Posta Rd – 2000 near Rancho Durango before paving in 2005



County Road 213 – Lower La Posta Rd – 8 mile Paving project 2005




County Road 213 / "River Road"– New Rivera Crossing Bridge 2004-05



County Road 234– just south of 235 – reconstruction 2009



County Road 120– south leg – paved road returned to gravel road in 2007



County Road 120– North leg – Impacts from Coal Mine traffic – 6.4 miles, 2.4 paved



County Road 120– North leg – loaded trucks – right lane – empty left lane



County Road 228– Road dust showing need for magnesium chloride – or other dust suppressant



County Road 232– Grandview gravel road - starting to see development pressure



County Road 250– Full depth reclamation project in 2012 – working within “right-of-way”



County Road 250– Full depth reclamation project completed in 2012



County Road 243– recent slide above Helen’s Store – new since 2002 fire